

TECHNICAL INFORMATION BULLETIN

FIRECLASS FC503, FC506 Firmware ver 01.02.01

1 General Note

This TIB refers to the:

- Factory release of FC503 FW version 01.02.01.
- Factory release of FC506 FW version 01.02.01.

Version 01.02.01 of FC503 and FC506 Panel Firmware are available for all applicable markets

The main contents of this release are:

- Support for 128 software zones for FC503 and 256 software zones for FC506
- Support for FIRECLASS FC503 Panel with FW version 01.02.01, in FCConsole version 01.02.01
- Support for FIRECLASS FC506 Panel with FW version 01.02.01, in FCConsole version 01.02.01

2 Upgrade from earlier version

Panels configured with FW version 01.01.00 or higher are directly compatible with version 01.02.01 FW. Firmware upgrade instructions are included in the installation manual 'section - FC503/6 Firmware upgrade quick guide'.

3 Technical Support

Please send Technical Support Issues to Techservices-Detection@tycoint.com